

Ontario Clean Water Agency Summary for the Township of Huron-Kinloss

Date: May 2026

WATER

LAKESHORE

Adverse Samples: None

Microbiological Sampling Summary: No adverse bacteriological sample results as of May 22nd

Non-Compliances/AWQI: None

Equipment Issues:

- Repaired faulty Tachmina in Point Clark
- Repaired leaking chlorine board in Point Clark
- Repaired leaking chlorine board in Blair's Grove
- Repaired leaking chlorine board in Murdoch Glen

Planned Maintenance:

- Collected Iron and Manganese samples
- New service installed at 800 Wilson Ave (private side)
- New service installed at 509 Abenaki Dr (private side)
- Completed SCADA integration for new generator in Point Clark
- Semi-annual hydrant flushing completed
- Debris removed from numerous valve boxes in the distribution

Main breaks and Leaks/Repairs:

- Repaired broken curbstop at 513 Abenaki Dr (new rod and pin)
- Repaired broken curbstop at 31 Birch St (new rod and pin)
- Cleaned out curbstop at 101 Blue St and confirmed operation
- Emergency shutoff for 935 Parkplace (leak on private side)

Power Outages: None

Complaints / Requests:

- Low pressure complaint at 607 Potawatomi Path (pressure was 60 psi)
- Low pressure complaint at 14 Scott Cres (private plumbing issue)

Locates: (see Township master list)

LUCKNOW

Adverse Samples: None

Microbiological Sampling Summary: No adverse bacteriological sample results as of May 22nd

Non-Compliances/AWQI: None

Ontario Clean Water Agency Summary for the Township of Huron-Kinloss

Equipment Issues:

- Repaired leaking chlorine board at Well 4
- Repaired faulty Tachmina at Well 4

Planned Maintenance:

- Semi-annual hydrant flushing completed
- ROV inspection completed at the Elevated Tank
- Debris removed from numerous valve boxes in the distribution

Main breaks and Leaks: None

Power Outages: None

Complaints / Requests: None

Locates: (see Township master list)

RIPLEY

Adverse Samples: None

Microbiological Sampling Summary: No adverse bacteriological sample results as of May 22nd

Non-Compliances/AWQI: None

Equipment Issues:

- Ripley ET mixer fault corrected after hydro interruption
- Repaired leaking chlorine board at Wellhouse

Planned Maintenance:

- Semi-annual hydrant flushing completed

Main breaks and Leaks: None

Power Outages:

- Brief outage on May 9th

Complaints / Requests: None

Locates: (see Township master list)

WHITECHURCH

Adverse Samples: None

Microbiological Sampling Summary: No adverse bacteriological sample results as of May 22nd

Non-Compliances/AWQI: None

Equipment Issues: None

Planned Maintenance:

- Semi-annual blowoff flushing completed
- MECP Inspector on-site for unannounced inspection (May 13th)

Main breaks and Leaks: None

Ontario Clean Water Agency Summary for the Township of Huron-Kinloss

Power Outages: None

Complaints / Requests: None

Locates: (see Township master list)

WASTEWATER

LUCKNOW

Exceedances: None

Non-Compliances: None

Equipment Issues:

- Continued diverting aerated lagoon flow to the storage lagoon. Received approval from MECP Inspector and met with BM Ross on October 31st to discuss possible solutions for poor drainage. Test holes dug on November 20th. Sourcing materials for filter rebuild
- Sludge removed from interconnecting chambers at the Lagoon

Planned Maintenance: None

Sewer Main Breaks and Leaks: None

Power Outages: None

Total Locates: (see Township master list)

RIPLEY

Exceedances: None

Non-Compliances: None

Equipment Issues:

- Failed SP2 replaced with new sewage pump

Planned Maintenance:

- Spring discharge completed (April 30th)
- Flushed sewers on Huron and Park st
- Main and Arena SPSs cleaned

Sewer Main Breaks and Leaks: None

Power Outages:

- Brief outage on May 9th

Complaints: None

Total Locates: (see Township master list)

Ontario Clean Water Agency Summary for the Township of Huron-Kinloss

Ongoing Issues/Recommendations

WATER:

Lakeshore

- Replace both HLP Singer valves with swing check valves in Point Clark
- Repair PSV on Concession 8

Ripley

- HLP piping replacement in the Ripley wellhouse.
- Replace Endress & Hauser analyzer at Elevated Tank

Lucknow

- Piping replacement in Lucknow well 4
- Replace Endress & Hauser analyzer at well 5

Whitechurch

- Replace Endress & Hauser analyzer

WASTEWATER:

Lucknow: None

Ripley: None