

Ontario Clean Water Agency Summary for the Township of Huron-Kinloss

Date: January 2026

WATER

LAKESHORE

Adverse Samples: None

Microbiological Sampling Summary: No adverse bacteriological sample results as of January 23rd

Non-Compliances/AWQI: None

Equipment Issues:

- HLP5 uncommanded start/failed to stop alarms corrected at Murdoch Glen
- Leaking chlorine board repaired at Huronville
- Failed chlorine pump repaired at Point Clark

Planned Maintenance:

- Completed quarterly sampling
- Repaired valve chamber at the bottom of Concession 6 after it was hit by a plow

Main breaks and Leaks:

- Leaking service repaired on private side of 547 Alfred st (Elliott's Construction)
- Emergency shut off at 978 Heritage Dr for a leak in their basement

Power Outages:

- Short outage on December 27th (all sites)
- Extended outage December 29th (all sites)
- Short outage on January 5th (Huronville)
- Extended outage on January 9th (Huronville)

Complaints / Requests: None

Locates: (see Township master list)

LUCKNOW

Adverse Samples: None

Microbiological Sampling Summary: No adverse bacteriological sample results as of January 23rd

Non-Compliances/AWQI: None

Equipment Issues:

- Repaired faulty Tachmina at well 4
- Repaired leaking chlorine board at well 4

Ontario Clean Water Agency Summary for the Township of Huron-Kinloss

Planned Maintenance:

- Completed quarterly sampling

Main breaks and Leaks:

- Watermain break repaired in front of 520 Rose
- Repaired leaking valve on Montgomery/Wheeler
- Repaired leaking valve on Campbell/Montgomery

Power Outages: None

Complaints / Requests: None

Locates: (see Township master list)

RIPLEY

Adverse Samples: None

Microbiological Sampling Summary: No adverse bacteriological sample results as of January 23rd

Non-Compliances/AWQI: None

Equipment Issues: None

Planned Maintenance:

- Completed quarterly sampling

Main breaks and Leaks: None

Power Outages: None

Complaints / Requests: None

Locates: (see Township master list)

WHITECHURCH

Adverse Samples: None

Microbiological Sampling Summary: No adverse bacteriological sample results as of January 23rd

Non-Compliances/AWQI: None

Equipment Issues: None

Planned Maintenance:

- Completed quarterly sampling

Main breaks and Leaks: None

Power Outages: None

Complaints / Requests: None

Locates: (see Township master list)

Ontario Clean Water Agency Summary for the Township of Huron-Kinloss

WASTEWATER

LUCKNOW

Exceedances: None

Non-Compliances: None

Equipment Issues:

- High flows at SPS due to thaw. Pumps were able to keep up

Planned Maintenance:

- Continued diverting aerated lagoon flow to the storage lagoon to allow the filter beds to drain. Received approval from MECP Inspector and met with BM Ross on October 31st to discuss possible solutions for poor drainage. Test holes dug on November 20th. Waiting on report from BM Ross for next steps

Sewer Main Breaks and Leaks: None

Power Outages: None

Total Locates: (see Township master list)

RIPLEY

Exceedances: None

Non-Compliances: None

Equipment Issues:

- Phone line/alarm dialer issues corrected
- High flows at SPS due to thaw. Pumps not able to keep up. Sewage hauler pumped out 387m³ to prevent overflow.

Planned Maintenance: None

Sewer Main Breaks and Leaks: None

Power Outages: None

Complaints: None

Total Locates: (see Township master list)

Ontario Clean Water Agency Summary for the Township of Huron-Kinloss

Ongoing Issues/Recommendations

WATER:

Lakeshore

- Replace both HLP Singer valves with swing check valves in Point Clark

Ripley

- HLP piping replacement in the Ripley wellhouse.
- Replace Endress & Hauser analyzer at Elevated Tank

Lucknow

- Piping replacement in Lucknow well 4
- Replace Endress & Hauser analyzer at well 5

Whitechurch

- Replace Endress & Hauser analyzer

WASTEWATER:

Lucknow:

- Waiting for electrician to source parts for pump install at lagoon. Ongoing
- Upgrade chemical feed pumps. Waiting on quotes

Ripley:

- Upgrade chemical feed pumps. Waiting on quotes