

Ontario Clean Water Agency Summary for the Township of Huron-Kinloss

Date: April 2026

WATER

LAKESHORE

Adverse Samples: None

Microbiological Sampling Summary: No adverse bacteriological sample results as of April 24th

Non-Compliances/AWQI: None

Equipment Issues:

- Repaired faulty Tachmina in Point Clark

Planned Maintenance:

- Leaking control valve for HLP1 at Murdoch Glen repaired
- Rebuilt motor for HLP1 at Point Clark installed
- Packing drain installed and pump head cleaned and painted for HLP5 at Murdoch Glen
- Repaired completed on seized curbstop for 102 Stratford St
- Quarterly samples collected

Main breaks and Leaks:

- Emergency shut off for 22 Boiler Beach Rd (leak on the private side)

Power Outages:

- Short outage on April 9th in Point Clark

Complaints / Requests:

- Rusty water complaint at 956 Bogdanovic Way
- High TDS complaint at 306 Lewis Rd

Locates: (see Township master list)

LUCKNOW

Adverse Samples: None

Microbiological Sampling Summary: No adverse bacteriological sample results as of April 24th

Non-Compliances/AWQI: None

Equipment Issues:

- Repaired leaking chlorine board at Well 4
- Replaced blown fuse on Well Pump 5 VFD

Planned Maintenance:

- Quarterly samples collected

Main breaks and Leaks: None

Ontario Clean Water Agency Summary for the Township of Huron-Kinloss

Power Outages: None

Complaints / Requests:

- Rusty water complaint at 655 Wheeler st

Locates: (see Township master list)

RIPLEY

Adverse Samples: None

Microbiological Sampling Summary: No adverse bacteriological sample results as of April 24th

Non-Compliances/AWQI: None

Equipment Issues: None

Planned Maintenance:

- Quarterly samples collected

Main breaks and Leaks: None

Power Outages:

- Brief outage on March 31st

Complaints / Requests: None

Locates: (see Township master list)

WHITECHURCH

Adverse Samples: None

Microbiological Sampling Summary: No adverse bacteriological sample results as of April 24th

Non-Compliances/AWQI: None

Equipment Issues: None

Planned Maintenance:

- Quarterly samples collected

Main breaks and Leaks: None

Power Outages: None

Complaints / Requests: None

Locates: (see Township master list)

WASTEWATER

LUCKNOW

Exceedances: None

Non-Compliances: None

Ontario Clean Water Agency Summary for the Township of Huron-Kinloss

Equipment Issues:

- Continued diverting aerated lagoon flow to the storage lagoon. Received approval from MECP Inspector and met with BM Ross on October 31st to discuss possible solutions for poor drainage. Test holes dug on November 20th. Waiting on report from BM Ross for next steps
- Broken cable holding Aerator 3 in place in cell 2 at the lagoons replaced

Planned Maintenance:

- MECP Inspector on-site for scheduled inspection (March 30th)
- SPS wet well cleaned and inspected
- Rebuilt SP1 installed at SPS

Sewer Main Breaks and Leaks: None

Power Outages: None

Total Locates: (see Township master list)

RIPLEY

Exceedances: None

Non-Compliances: None

Equipment Issues:

- High flows at SPS due to heavy rain. Pumps not able to keep up. Spill on March 31st - Ref# 1-QG0QOA reported to the Ministry and Health Unit with a total estimated volume of 69m³. Sewage haulers pumped out 750m³ from the collection system to mitigate spill volume
- High flows at SPS due to heavy rain. Pumps not able to keep up. Spill on April 15th - Ref# 1-QIR5PL reported to the Ministry and Health Unit with a total estimated volume of 14m³. Sewage haulers pumped out 444m³ from the collection system to mitigate spill volume
- High flows at SPS due to heavy rain on April 16th. Pumps barely able to keep up, sewage haulers pumped out 414m³ from the collection system to prevent a spill.
- Failed SP2 removed and sent away for repair

Planned Maintenance:

- Spring discharge continues
- Grease cleaned out of last manhole before SPS

Sewer Main Breaks and Leaks: None

Power Outages: None

Complaints: None

Total Locates: (see Township master list)

Ontario Clean Water Agency Summary for the Township of Huron-Kinloss

Ongoing Issues/Recommendations

WATER:

Lakeshore

- Replace both HLP Singer valves with swing check valves in Point Clark

Ripley

- HLP piping replacement in the Ripley wellhouse.
- Replace Endress & Hauser analyzer at Elevated Tank

Lucknow

- Piping replacement in Lucknow well 4
- Replace Endress & Hauser analyzer at well 5

Whitechurch

- Replace Endress & Hauser analyzer

WASTEWATER:

Lucknow: None

Ripley: None