

Ontario Clean Water Agency Summary for the Township of Huron-Kinloss

Date: June 2026

WATER

LAKESHORE

Adverse Samples: None

Microbiological Sampling Summary: No adverse bacteriological sample results as of June 26th

Non-Compliances/AWQI: None

Equipment Issues:

- Repaired faulty Tachmina in Point Clark
- Repaired leaking chlorine board in Point Clark
- Repaired faulty sodium silicate pump in Point Clark
- Repaired leaking chlorine board in Blairs Grove
- Repaired leaking chlorine board in Murdoch Glen
- Repaired leaking chlorine board in Huronville

Planned Maintenance:

- Collected Iron and Manganese samples
- Annual instrumentation calibrations completed
- Annual generator services completed
- Completed watermain commissioning for new main on Boiler Beach (not in service yet)
- New service installed at 38 Penetangore Row S
- New service installed at 34 Penetangore Row S
- MECP Inspector on-site for annual inspection (June 23rd)

Main breaks and Leaks/Repairs:

- Repaired watermain break beside 2 Penetangore Row S
- Repaired broken curbstop for 731 Victoria (new cap)
- Emergency shut off for 719 Victoria Rd (leak on private side)
- Repaired broken curbstop at 806 Meadow Pl (new cap)
- Emergency shut off for 3 Green Brae Cres (leak on private side)
- Repaired leaking service for 711 Walpole Trail
- Emergency shut off for 48 Penetangore Row S (leak on private side)
- Emergency shut off for 1 Bell Dr (leak on private side)
- Repaired watermain break behind 32 Penetangore Row
- Repaired broken curbstop for 341 Kris St (new box)

Power Outages: None

Ontario Clean Water Agency Summary for the Township of Huron-Kinloss

Complaints / Requests:

- Low pressure at 8 Hwy 21 (pressure was 35psi)
- Low pressure at 76 Lake Range Dr (pressure was 47psi)
- Low pressure on Penetangore Row due to watermain break

Locates: (see Township master list)

LUCKNOW

Adverse Samples: None

Microbiological Sampling Summary: No adverse bacteriological sample results as of June 26th

Non-Compliances/AWQI: None

Equipment Issues:

- Repaired leaking chlorine board at Well 4
- Repaired faulty Tachmina at Well 4
- Elevated tank/SCADA communications issues resolved

Planned Maintenance:

- Four cut and caps completed to isolate the Ross st PS from the distribution system
- Annual instrumentation calibrations completed
- Annual generator service completed
- OCWA water buggy setup for Dungannon Super Pull at Graceland Festival Grounds

Main breaks and Leaks: None

Power Outages: None

Complaints / Requests:

- Low pressure/no water on Palmerston st (due to cut and cap/isolation work for the Ross st PS)

Locates: (see Township master list)

RIPLEY

Adverse Samples: None

Microbiological Sampling Summary: No adverse bacteriological sample results as of June 26th

Non-Compliances/AWQI: None

Equipment Issues:

- Replaced faulty block heater on Arena/ET generator
- Repaired leaking chlorine board at Wellhouse

Planned Maintenance:

- Annual instrumentation calibrations completed
- Annual generator services completed

Ontario Clean Water Agency Summary for the Township of Huron-Kinloss

- Completed watermain commissioning for temporary main on Park st (not in service yet)

Main breaks and Leaks: None

Power Outages: None

Complaints / Requests: None

Locates: (see Township master list)

WHITECHURCH

Adverse Samples: None

Microbiological Sampling Summary: No adverse bacteriological sample results as of June 26th

Non-Compliances/AWQI: None

Equipment Issues:

- Replaced faulty UPS
- Repaired chlorine system leak on Well 2
- Repaired faulty chlorine pump for Well 1
- Replaced faulty start capacitor and Grundfos pump panel for Well 1

Planned Maintenance:

- Annual instrumentation calibrations completed
- Repaired Contact Main blowoff outside wellhouse

Main breaks and Leaks: None

Power Outages: None

Complaints / Requests: None

Locates: (see Township master list)

WASTEWATER

LUCKNOW

Exceedances: None

Non-Compliances:

- Monthly average groundwater ammonia concentration non-compliance reported to the Ministry (for May) on June 3rd

Equipment Issues:

- Continued diverting aerated lagoon flow to the storage lagoon. Received approval from MECP Inspector and met with BM Ross on October 31st to discuss possible solutions for poor drainage. Test holes dug on November 20th. Sourcing materials for filter rebuild

Ontario Clean Water Agency Summary for the Township of Huron-Kinloss

Planned Maintenance:

- Annual instrumentation calibrations completed
- Sludge survey conducted at Lagoon

Sewer Main Breaks and Leaks:

- Damaged cleanout cap replaced at 443 Havelock st

Power Outages: None

Total Locates: (see Township master list)

RIPLEY

Exceedances: None

Non-Compliances: None

Equipment Issues:

- Spare SP purchased and delivered to SPS

Planned Maintenance:

- Annual instrumentation calibrations completed
- Annual generator service completed
- Sludge survey conducted at Lagoon

Sewer Main Breaks and Leaks: None

Power Outages: None

Complaints: None

Total Locates: (see Township master list)

Ongoing Issues/Recommendations

WATER:

Lakeshore

- Replace both HLP Singer valves with swing check valves in Point Clark
- Repair PSV on Concession 8

Ripley

- HLP piping replacement in the Ripley wellhouse.
- Replace Endress & Hauser analyzer at Elevated Tank (ordered)

Lucknow

- Piping replacement in Lucknow well 4
- Replace Endress & Hauser analyzer at well 5 (ordered)

Ontario Clean Water Agency Summary for the Township of Huron-Kinloss

Whitechurch

- Replace Endress & Hauser analyzer (ordered)

WASTEWATER:

Lucknow: None

Ripley: None