

**Township of Huron-Kinloss
Point Clark Water Quality Monitoring Program
2006 Sampling Results**

E.Coli cfu/100ml

SAMPLE ID	LOCATION	1-May	15-May	29-May	12-Jun	26-Jun	10-Jul	24-Jul	9-Aug	21-Aug	5-Sep	18-Sep	2-Oct	16-Oct
B1	Beach at 917 Cedar Trail	9	38	41	7	56	350	720	27	84	98	1400	120	15
B2	Beach at Lighthouse swimming area --same as PR22	<2	20	28	23	62	160	36	79	38	6	400	22	17
B3	Beach at 755 Victoria	0	8	6	9	18	140	13	42	10	1	400	5	24
B4	Clark Creek at the Lake	125	2250	410	550	174	2900	210	78	260	140	87	310	3800
4	Jardine Creek at Walpole Trail	400	20	130	610	1030	6600	760	2300	270	230	270	600	170
5	Ditch at field drain outlet, Lake Range Road	410	172	860	1960	720	dry	dry	dry	dry	dry	dry	600	1180
6	New outlet to Clark Creek across from 3491 2nd Conc.	0	1	11	13	72	230	47	12	20	220	17	6	200
8	Jardine Creek at Abenaki St.	2010	6600	630	460	no flow	880	1770	5200	710	1720	no flow	4400	3300
9	Jardine Creek at Seneca	110	280	660	1210	n.a.	n/a	n/a	370	620	no flow	340	500	70
11	Off foot bridge at beach	126	92	210	330	550	3510	410	38	29	450	430	640	790
12	Halfway to lake from Road	210	60	174	61	610	8800	180	340	500	103	36	260	38
13	CSP where creek crosses Huron Rd.	790	1280	188	112	134	7400	470	600	520	101	530	121	39
16	Outlet at Lake Range Dr. and Attawandaron Rd.	dry	dry	dry	dry	dry	dry	dry	dry	dry	dry	dry	dry	dry
17	Outlet in Jardine Creek between sites 11 & 12	38	0	290	350	1450	124	7	16	260	2250	980	5300	1930