

**Township of Huron-Kinloss
Point Clark Water Quality Monitoring Program
2005 Sampling Results**

E.Coli cfu/100ml

SAMPLE ID	LOCATION	2-May	16-May	30-May	14-Jun	27-Jun	11-Jul	25-Jul	8-Aug	22-Aug	6-Sep	19-Sep	3-Oct	17-Oct.
B1	Beach at 917 Cedar Trail	30	110	20	260	28	42	250	380	110	130	210	78	39
B2	Beach at Lighthouse swimming area --same as PR22	80	40	5	220	6	33	200	6	180	20	82	27	25
B3	Beach at 755 Victoria	60	12	0	1400	3	16	135	7	150	8	30	28	11
B4	Clark Creek at the Lake	60	100	160	1500	290	100	260	52	230	10	88	720	420
4	Jardine Creek at Walpole Trail	30	670	450	1400	500	700	No Flow	24000	1500	170	No Flow	1400	6
5	Ditch at field drain outlet, Lake Range Road	190	6400	130	9300	Dry	Dry	Dry	Dry	Dry	Dry	Dry	Dry	Dry
6	New outlet to Clark Creek across from 3491 2nd Conc.	1	6	2	3200	30	11	15	5	15000	1	2	820	6
8	Jardine Creek at Abenaki St.	70	150	1500	4200	No Flow	No Flow	No Flow	No Flow	5000	No Flow	No Flow	9300	10200
9	Jardine Creek at Seneca	20	10	160	3400	1100	7500	2000	1500	310	500	11000	4900	1200
11	Off foot bridge at beach	180	260	370	3300	1600	7000	1200	680	1700	2700	340	4200	3300
12	Halfway to lake from Road	300	1200	210	5000	110	640	No Flow	360	39	0	No Flow	150	180
13	CSP where creek crosses Huron Rd.	110	150	5000	3400	200	1500	No Flow	No Flow	7000	No Flow	No Flow	780	3000
16	Outlet at Lake Range Dr. and Attawandaron Rd.		3	5	24	Dry	Dry	Dry	Dry	Dry	Dry	Dry	Dry	Dry
17	Outlet in Jardine Creek between sites 11 & 12		0	240	940	1200	6600	700	1200	11000	0	9700	8300	14600