Municipality of Huron-Kinloss
Pine River Water Quality Monitoring Program
2010 Sampling Results

Hydrogen Sulphide (mg/L)
Sample Date

SAMPLE ID	LOCATION	26-Apr	21-Jun	5-Jul	20-Jul	17-Aug	14-Sep	13-Oct	9-Nov	
PR7 - Upstream	Clark Creek-Culvert on Sideroad 25 South of 4th Conc.	<0.02	<0.02	<0.02	0.02	<0.02	<0.02	<0.02	<0.02	
PR7 - Outlet	Clark Creek-Culvert on Sideroad 25 South of 4th Conc.	0.43	1.71	4.39	3.53	6.13	7.4	<0.02	0.04	
PR17 - Upstream	Pine River Tributary-Southern Culvert on South Baseline Road North of 4th Conc.	<0.02	<0.02							
PR17 - Outlet	Pine River Tributary-Southern Culvert on South Baseline Road North of 4th Conc.									
PR18 - Upstream	Pine River Tributary- Middle Culvert on South Baseline Road North of 4th Conc.	<0.02	<0.02	<0.02	0.02	0.09	dry	<0.02	<0.02	
PR18 - Outlet	Pine River Tributary- Middle Culvert on South Baseline Road North of 4th Conc.	0.48	0.037	0.02	0.02	3.3	dry	0.08	<0.02	
PR19 - Upstream	Clark Creek-Southern Culvert on South Baseline Road North of 2nd Conc.	<0.02	<0.02		0.02					
PR19 - Outlet	Clark Creek-Southern Culvert on South Baseline Road North of 2nd Conc.	0.39								