Municipality of Huron-Kinlos
Pine River Water Quality Monitoring Program
2014 Sampling Result

Total Suspended Solids - TSS (mg/L)

SAMPLE ID	LOCATION	Sample Date								
		28-Apr	27-May	24-Jun	22-Jul	19-Aug	16-Sep	15-Oct	11-Nov	
PR1	Pine River-'Bridge on Lake Range Road, south of Lurgan Road	20	9	81	13	28	16	11	10	
PR3	South Pine River-Bridge on Hwy. 21 at 6th Conc.	12	7	9	8	29	10	6	9	
PR4	Pine River Tributary-Bridge on Hwy. 21 North of 6th Conc.	9	5	9	9	16	7	6	12	
PR5	Pine River Tributary-Bridge on Hwy. 21 North of 8th Conc.	17	8	17	15	23	25	22	19	
PR6	South Pine River-Bridge on Sideroad 25 North of 6th Conc.	13	8	9	8	10	8	6	8	
PR8	South Pine River-Culvert on the 15th North of 6th Conc.	7	4	6	7	6	5	4	7	
PR9	Pine River-Bridge on the 15th South of 10th Conc.	4	7	3	<2	3	5	3	6	
PR10	Royal Oak Creek-Bridge on the 15th North of the 12th Conc.	5	3	4	3	11	6	46	6	
PR11	Royal Oak Creek-Cuvlert on Sideroad 5 north Huron-Kincardine East	<2	5	3	8	5	29	34	8	
PR12	Pine River-Bridge on Huron Twp./Kinloss Twp. Boundary South of 12th Conc.	3	6	10	9	5	4	22	2	
PR13	South Pine River-Bridge on Huron Twp./Kinloss Twp. Boundary South of 8th Conc	7	55	5	10	Dry	3	36	7	
PR17 - Upstream	Pine River Tributary-Southern Culvert on South Baseline Road North of 4th Conc.	6	4	3	6	Dry	8	18	10	
PR18 - Upstream	Pine River Tributary- Middle Culvert on South Baseline Road North of 4th Conc.	5	2	9	18	21	3	4	2	