Municipality of Huron-Kinlos
Pine River Water Quality Monitoring Prograr
2015 Sampling Result

Total Suspended Solids - TSS (mg/L)

SAMPLE ID	LOCATION	Sample Date								
		07-Apr	28-Apr	26-May	23-Jun	21-Jul	18-Aug	14-Sep	13-Oct	10-Nov
PR1	Pine River-'Bridge on Lake Range Road, south of Lurgan Road	72	5	4	150	10	14	8	6	3
PR3	South Pine River-Bridge on Hwy. 21 at 6th Conc.	40	6	9	10	7	7	2	11	3
PR4	Pine River Tributary-Bridge on Hwy. 21 North of 6th Conc.	35	5	6	40	14	8	5	4	4
PR5	Pine River Tributary-Bridge on Hwy. 21 North of 8th Conc.	32	7	20	131	12	8	12	11	8
PR6	South Pine River-Bridge on Sideroad 25 North of 6th Conc.	24	2	3	12	10	14	28	30	3
PR8	South Pine River-Culvert on the 15th North of 6th Conc.	16	< 2	6	24	13	17	6	3	3
PR9	Pine River-Bridge on the 15th South of 10th Conc.	8	2	7	4	3	8	< 2	6	< 2
PR10	Royal Oak Creek-Bridge on the 15th North of the 12th Conc.	14	3	6	12	8	4	2	5	2
PR11	Royal Oak Creek-Cuvlert on Sideroad 5 north Huron-Kincardine East	< 6	< 2	8	13	5	35	< 2	5	2
PR12	Pine River-Bridge on Huron Twp./Kinloss Twp. Boundary South of 12th Conc.	7	2	6	11	8	28	7	5	< 2
PR13	South Pine River-Bridge on Huron Twp./Kinloss Twp. Boundary South of 8th Conc	7	< 2	8	56	2	9	6	9	3
PR17 - Upstream	Pine River Tributary-Southern Culvert on South Baseline Road North of 4th Conc.	7	5	4	15	< 2	10	13	15	11
PR18 - Upstream	Pine River Tributary- Middle Culvert on South Baseline Road North of 4th Conc.	12	< 2	2	13	27	13	6	5	< 2