

**Municipality of Huron-Kinloss
Pine River Water Quality Monitoring Program
2012 Sampling Results**

Total Suspended Solids (mg/L)

SAMPLE ID	LOCATION	Sample Date							
		02-Apr-12	30-Apr-12 01-May-12						
PR1	Pine River-Bridge on Lake Range Road, south of Lurgan Road	5	3						
PR3	South Pine River-Bridge on Hwy. 21 at 6th Conc.	3	2						
PR4	Pine River Tributary-Bridge on Hwy. 21 North of 6th Conc.	3	10						
PR5	Pine River Tributary-Bridge on Hwy. 21 North of 8th Conc.	7	23						
PR6	South Pine River-Bridge on Sideroad 25 North of 6th Conc.	4	4						
PR7 - Upstream	Clark Creek-Culvert on Sideroad 25 South of 4th Conc.	<2	5						
PR8	South Pine River-Culvert on the 15th North of 6th Conc.	2	2						
PR9	Pine River-Bridge on the 15th South of 10th Conc.	2	5						
PR10	Royal Oak Creek-Bridge on the 15th North of the 12th Conc.	2	2						
PR12	Pine River-Bridge on Huron Twp./Kinloss Twp. Boundary South of 12th Conc.	2	3						
PR13	South Pine River-Bridge on Huron Twp./Kinloss Twp. Boundary South of 8th Conc	<2	2						
PR17 - Upstream	Pine River Tributary-Southern Culvert on South Baseline Road North of 4th Conc.	2	<2						
PR18 - Upstream	Pine River Tributary- Middle Culvert on South Baseline Road North of 4th Conc.	<2	3						
PR19 - Upstream	Clark Creek-Southern Culvert on South Baseline Road North of 2nd Conc.	2	10						
PR20	Beach at Hwy. 86 -Amberely Road.	16	5						
PR21	Beach off of Attawandron Road-Public Walkway	16	10						
PR22	Beach-Point Clark Swimming Area	40	3						
PR23	Lurgan Beach-Public Walkway	12	3						
PR24	Beach at 6th Conc.	20	7						
PR25	Beach at 8th Conc.	22	2						
PR26	Beach at 10th Conc.	26	<2						
PR27	Boyd Creek at Hwy. 21 before Amberely	<2	5						
PR29	Boyd Creek on Sideroad 20 North of 6th Conc.	3	2						
PR30	Eighteen Mile Creek at Hwy. 21 before Amberely	6	3						
PR32	Eighteen Mile Creek on the 15th North of 2nd Conc.	2	2						

n/s = No sample