

**Municipality of Huron-Kinloss
Point Clark Water Quality Monitoring Program
2010 Sampling Results**

E. Coli (cfu/100mL)

SAMPLE ID	LOCATION	Sample Date													
		3-May	31-May	7-Jun	21-Jun	5-Jul	19-Jul	3-Aug	16-Aug	30-Aug	13-Sep	27-Sep	12-Oct	26-Oct	
B1	Beach at 917 Cedar Trail	6	52	1110	4	1	389	29	21	31	209	25	25	40	
B2	Beach at Lighthouse swimming area --same as PR22	3	14	860	10	2	262	22	28	16	24	15	12	35	
B3	Beach at 755 Victoria	6	61	400	27	0	560	21	43	8	17	7	20	12	
B4	Clark Creek at the Lake	350	129	660	72	51	3580	79	790	560	193	920	90	116	
4	Jardine Creek at Walpole Trail	26	108	73	99	203	1150	380	91	34	33	42	730	6	
5	Ditch at field drain outlet, Lake Range Road	3	1360	1030	171	64	1190	47	62	dry	dry	32	40	74	
6	New outlet to Clark Creek across from 3491 2nd Conc.	26	116	640	88	40	1830	72	770	116	104	47	20	610	
8	Jardine Creek at Abenaki St.	220	22	100	31	64	820	140	660	28	79	4	<10	11	
9	Jardine Creek at Seneca	dry	dry	84	148	1710	196	50	dry	dry	dry	dry	dry	dry	
11	Off foot bridge at beach	200	101	68	106	69	850	40	71	29	21	36	20	8	
12	Halfway to lake from Road	28	150	73	108	109	1270	66	76	44	26	23	1860	0	
13	CSP where creek crosses Huron Rd.	54	76	73	142	930	590	30	280	600	84	24	630	4	
16	Outlet at Lake Range Dr. and Attawandaron Rd.	dry	dry	430	dry	dry	dry	dry	dry	dry	dry	dry	dry	dry	
17	Outlet in Jardine Creek between sites 11 & 12	67	70	58	77	59	530	17	27	44	7	3	610	2	