

**Municipality of Huron-Kinloss
Point Clark Water Quality Monitoring Program
2014 Sampling Results**

E. Coli (cfu/100mL)

SAMPLE ID	LOCATION	Sample Date														
		28-Apr	12-May	27-May	9-Jun	23-Jun	7-Jul	21-Jul	5-Aug	18-Aug	2-Sep	15-Sep	30-Sep	14-Oct	28-Oct	10-Nov
B1	Beach at 917 Cedar Trail	0	9	46	130	40	380	1	300	10	106	40	37	79	38	72
B2	Beach at Lighthouse swimming area --same as PR22	0	7	6	31	1	93	1	28	5	61	22	53	8	37	118
B3	Beach at 755 Victoria	0	0	3	28	3	540	0	21	7	49	30	74	16	23	187
B4	Clark Creek at the Lake	12	104	55	97	150	70	142	250	94	1970	510	1280	99	132	270
4	Jardine Creek at Walpole Trail	1	3	132	530	300	370	113	4400	78	800	20	112	3	3	11
5	Ditch at field drain outlet, Lake Range Road	144	350	250	1160	Dry	7400	173	n/s	Dry	Dry	3800	7400	1110	1540	245
6	New outlet to Clark Creek across from 3491 2nd Conc.	50	43	54	58	162	50	115	114	84	1150	450	820	121	101	250
8	Jardine Creek at Abenaki St.	3	24	6	540	86	850	10	24	46	2010	121	510	3600	10800	1020
9	Jardine Creek at Seneca	2	124	109	170	n/s	n/s	n/s	n/s	n/s	n/s	n/s	520	n/s	n/s	n/s
11	Off foot bridge at beach	5	1	94	40	670	450	59	610	2430	4800	480	1110	1210	156	137
12	Halfway to lake from Road	2	2	250	65	140	99	310	33	34	590	69	730	1	5	2
13	CSP where creek crosses Huron Rd.	5	81	660	1880	440	165	119	250	200	750	54	240	43	60	1080
16	Outlet at Lake Range Dr. and Attawandaron Rd.	1	Dry	Dry	Dry	Dry	Dry	Dry	Dry	Dry	Dry	Dry	880	Dry	Dry	4
17	Outlet in Jardine Creek between sites 11 & 12	6	6	150	26	29	145	26	1520	2550	3800	280	650	1080	450	168

n/s = no sample