

**Municipality of Huron-Kinloss
Point Clark Water Quality Monitoring Program
2009 Sampling Results**

E. Coli (cfu/100mL)

SAMPLE ID	LOCATION	Sample Date											
		4-May	25-May	3-Jun	24-Jun	6-Jul	20-Jul	4-Aug	17-Aug	31-Aug	14-Sep	1-Oct	29-Oct
B1	Beach at 917 Cedar Trail	9	19	1160	33	20	21	130	256	25	220	38	30
B2	Beach at Lighthouse swimming area --same as PR22	21	14	17	1	1	35	116	560	73	226	59	4
B3	Beach at 755 Victoria	14	61	21	1	9	10	129	84	19	89	34	6
B4	Clark Creek at the Lake	72	124	330	180	330	19	29	127	307	73	166	36
4	Jardine Creek at Walpole Trail	200	56	120	430	107	68	790	8600	4790	54	930	23
5	Ditch at field drain outlet, Lake Range Road	1740	147	115	2200	75	920	Dry	Dry	Dry	Dry	Dry	Dry
6	New outlet to Clark Creek across from 3491 2nd Conc.	117	24	21	20	48	11	11	520	19	60	127	68
8	Jardine Creek at Abenaki St.	650	33	420	230	82	260	53	6200	311	79	510	1570
9	Jardine Creek at Seneca	12	72	98	Dry	Dry	Dry	Dry	Dry	Dry	Dry	Dry	Dry
11	Off foot bridge at beach	18	65	81	440	220	490	114	1180	27	310	141	1830
12	Halfway to lake from Road	100	18	2	360	36	18	64	78	126	8	760	13
13	CSP where creek crosses Huron Rd.	520	890	196	9200	2400	840	4000	9200	144		1100	310
16	Outlet at Lake Range Dr. and Attawandaron Rd.	Dry	Dry	Dry	Dry	Dry	Dry	Dry	Dry	Dry	Dry	Dry	Dry
17	Outlet in Jardine Creek between sites 11 & 12	1	102	97	1330	82	9	6800	101	11	830	163	1920